

This firmware update is for all D756USTi and DH759USTi Ultra Short Throw Projectors

### Fixes & Improvements:

- Fixed calibration not working correctly on Windows 10
- Fixed double click not working on Windows 10 (build 1607) Anniversary update and above
- Improved ambient light handling
- Improved tracking

### Note:

[NovoPointer version 2.1.42.203](#) **needs** to be installed on the computer before continuing to update process.

## 1. Download & prepare


### Preparation:

1.1 Download the firmware file from the link below:

- 1 Firmware: [Download](#)

## 2. Update Process

2.1 Update the firmware




- 1) Start the NovoPointer application
- 2) Click on the “Settings” button

#### Note:

For the next update step, your status must be shown as “connected”. Re-connect the USB cable to the projector if the menu shows ‘Disconnected’.




3) Click on the “IM Upgrade” button.



4) Select the bin file:  
① (interactive\_module20171020\_FP05.bin)

**DO NOT UNPLUG OR SHUT DOWN THE COMPUTER DURING THE UPGRADE PROCESS**



5) The update progress message will be displayed. Wait for the update to complete to 100 percent




6) Once the update completed, click on the “Reset” button.

*Note:*

*If USB does not connect after pressing reset, unplug the USB cable and reconnect it.*


### 3. Confirm the version of the software

3.1 Confirm if your firmware update has been done successfully by reading the firmware version.



- 1) Go to Settings on the main menu of NovoPointer.
- 2) Confirm the version by clicking on the "Get IM Ver" button.

The latest version is **20171020\_FP05**



The update is now completed!